

NORTHEAST LUMBER COATERS

SPORE-NO-MORE

100% ACRYLIC CLEAR MOLD INHIBITING COATING

PRODUCT DESCRIPTION:

A custom formulated clear mold inhibiting coating designed for use over a variety of wood, masonry and composite materials that have been remediated from mold, mildew and a variety of contaminants. An excellent choice for those areas that are hard to get to, such as attics, crawl spaces, etc. where mold is likely to re-grow. Proprietary fungicide that outperforms most traditional fungicides as tested by against ASTM D-3273-05 and ASTM D3274-02. Especially effective against known organisms: Aspergillus niger, Aspergillus oryzae and certain species of Penicillium.

RECOMMENDED USES:

Interior wood as found in attics and crawl spaces. Painted or unpainted cellar walls and ceilings. Garage walls and ceilings. Exterior foundations, masonry, concrete or block walls. Any of aforementioned surfaces that have been treated with SPORE-NO-MORE spray-on mold and fungal remediation liquid.

Characteristics:

Vehicle: 100% Acrylic

Finish: Satin Gloss

Spread Rate: App. 400 sf per gallon depending on porosity of substrate

Drying Time: To touch: 1 hour To recoat: 4 hours

Weight Per Gallon: 10.63 lbs.

Percent solids/volume: 36.06

Percent solids by weight: 49.87

Viscosity: 105-110 Ku's

Recommended film thickness: 5 wet mils, 1.8 dry

Flammability: Non-Flammable

VOC's Less Water: 44.3 grams per liter, .37 lbs. per gallon

SURFACE PREPARATION:

14 Eastern Park Road, East Hartford, CT 06108
860-218-2210

NORTHEAST LUMBER COATERS

Remove all contamination via spray, brush, roll or pad application with SPORE-NO-MORE fungal remediation liquid. No rinsing necessary on interior surfaces. Dark discoloration should disappear. Exterior surfaces that will be painted with an opaque coating, apply SPORE-NO-MORE, allow 20 minutes and rinse with copious amounts of water. Wait to dry completely prior to applying paint or stain.

APPLICATION AND REDUCTION:

Thinning is not recommended. Apply at temperatures above 50 deg. F. Protect from freezing.

CLEAN-UP INFORMATION:

Clean up equipment and area with detergent and water.